


















NO	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
1	<p>PERBAIKAN LIFT AKASIA PASSENGER 1</p> <p><i>REPAIR ELEVATOR AKASIA PASSENGER 1</i></p>	<p>TOWER AKASIA</p> <p><i>AKASIA TOWER</i></p>		
2	<p>PERBAIKAN POMPA TREATMENT</p> <p><i>REPAIR PUMP OF TREATMENT</i></p>	<p>RUANG POMPA TREATMENT</p> <p><i>PUMP TREATMENT ROOM</i></p>		
3	<p>PERBAIKAN PANEL HUNIAN</p> <p><i>REPAIR RESIDENTIAL PANEL</i></p>	<p>TOWER CENDANA LANTAI 2</p> <p><i>CENDANA TOWER FLOOR 2ND</i></p>		

	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
4	<p>PREVENTIVE POMPA BOOSTER ROOF</p> <p><i>PREVENTIVE PUMP OF BOOSTER ROOF</i></p>	<p>SEMUA TOWER</p> <p><i>ALL TOWER</i></p>		
5	<p>PENAMBAHAN ANGIN PRESSURE TANK POMPA AIR TANAH</p> <p><i>ADDITIONAL WIND PRESSURE TANK GROUND WATER PUMP</i></p>	<p>RUANG POMPA AIR TANAH</p> <p><i>GROUND WATER PUMP ROOM</i></p>		
6	<p>PERBAIKAN POMPA TRANSFER AIR BERSIH CENDANA NO.1</p> <p><i>REPAIR TRANSFER OF WATER CLEAN CENDANA NUMBER ONE</i></p>	<p>RUANG POMPA CENDANA</p> <p><i>CENDANA PUMP ROOM</i></p>		







	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
7	<p>PERAPIHAN KABEL TV DAN STOP KONTAK</p> <p><i>CLEAN UP CABLE TV AND OUTLET</i></p>	<p>RUANG FITNESS</p> <p><i>FITNESS ROOM</i></p>		
8	<p>PERBAIKAN PIPA AIR KOTOR</p> <p><i>REPAIR OF DIRTY WATER PIPE</i></p>	<p>TOILET CENDANA BASEMENT</p> <p><i>TOILET ROOM CENDANA BASEMENT</i></p>		
9	<p>PENAMBAHAN PENERANGAN (LAMPU TL 4PCS)</p> <p><i>ADDITIONAL LIGHTING (LAMP OF TL 4 PCS)</i></p>	<p>PARKIRAN MOTOR PENGHUNI</p> <p><i>MOTORCYCLE PARKING OF RESIDENCE</i></p>		

	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
10	<p>PENAMBAHAN CCTV DI BASEMENT</p> <p><i>ADDITIONAL CCTV IN THE BASEMENT</i></p>	<p>DIDEPAN RUANG ENGINEERING</p> <p><i>IN FRONT OF ENGINEERING ROOM</i></p>		
11	<p>PERTUNJUKKAN BARONGSAI PADA HARI RAYA IMLEK</p> <p><i>PERFORMANCES ON HOLIDAY LUNAR BARONGSAI</i></p>	<p>SEMUA TOWER</p> <p><i>ALL TOWER</i></p>		
12	<p>PERBAIKAN CUBICLE TM OUT-GOING A1/B1 DAN A2/B2</p> <p><i>SERVICE CUBICLE TM OUT-GOING A1/B1 AND A2/B2</i></p>	<p>GARDU TM</p> <p><i>SUBSTATION OF TM</i></p>		

	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
13	<p>PEMASANGAN KWH/METER LISTRIK 3 PHASE</p> <p><i>INSTALLATION KWH/ELECTRICITY METER THREE OF PHASE</i></p>	<p>FLAMBOYAN DASAR 03</p> <p><i>BASE OF FLAMBOYAN 03</i></p>		
14	<p>PEMASANGAN KWH/METER LISTRIK 3 PHASE</p> <p><i>INSTALLATION KWH/ELECTRICITY METER THREE OF PHASE</i></p>	<p>DASAR AKASIA 01</p> <p><i>BASE OF AKASIA 01</i></p>		
15	<p>GANTI LAMPU SANGKAR DALAM LIFT EBONY</p> <p><i>CHANGES OF LAMP CAGE IN LIFT</i></p>	<p>EBONY P2</p> <p><i>EBONY P2</i></p>		

	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
16	PERBAIKAN PIPA INDUK AIR KOTOR <i>REPAIR OF DIRTY WATER MAIN PIPE</i>	ASTER DASAR 01 <i>BASE OF ASTER 01</i>		
17	PERBAIKAN DRAIN BALKON YANG MAMPET <i>DRAIN REPAIR BALCONY NOT GOING</i>	ASTER LANTAI 21/01 <i>ASTER FLOOR 21/01</i>		
18	PENAMBALAN JALAN YANG BERLUBANG <i>PATCHING ROADS OF PERFORATED</i>	DASAR AKASIA <i>BASE OF AKASIA</i>		

	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
19	PERBAIKAN PANEL HYDRANT <i>SERVICE PANEL OF HYDRANT</i>	RUANG POMPA CENDANA <i>PUMP CENDANA ROOM</i>		
20	PERBAIKAN INSTALASI LAMPU <i>REPAIR OF INSTALLATION LAMP</i>	RUANG FITNESS <i>FITNESS ROOM</i>		
21	PERBAIKAN KEBOCORAN PIPA AIR HUJAN <i>REPAIR LEAKING PIPE OF WATER RAIN</i>	FLAMBOYAN LANTAI 16/01 <i>FLAMBOYAN FLOOR 16/01</i>		

	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
22	PERBAIKAN LIFT ERROR DI LANTAI 1 <i>SERVICE ERROR LIFT AT FLOOR 1</i>	AKASIA P2 <i>AKASIA P2</i>		
23	PERBAIKAN NAT KERAMIK DINDING <i>CERAMIC OF WALL REPAIR</i>	DIDEPAN RUANG SAUNA <i>IN FRONT OF SAUNA ROOM</i>		
24	PERBAIKAN KEBOCORAN DENGAN TATA CARA MEBUAT TALANG <i>REPAIR OF LEAKING PROCEDURES TO MAKE OF TALANG</i>	KANTOR CITY PARKING <i>CITY PARKING OFFICE</i>		

	JOB DESCRIPTION	LOCATION	PICTURE	PICTURE
25	<p>PEMBUATAN WORKSHOP ENGINEERING DAN LIFT</p> <p><i>MAKING OF WORKSHOP ENGINEERING AND LIFT</i></p>	<p>DIDEPAN RUANG ENGINEERING</p> <p><i>IN FRONT OF ENGINEERING ROOM</i></p>		
26	<p>PENCOPOTAN BEL YANG BERBUNYI SEPERTI ALARM</p> <p><i>TAKEDOWN BEL AS THE RING OF ALARM</i></p>	<p>ASTER FLOOR 17/01</p> <p><i>ASTER FLOOR 17/01</i></p>		
27	<p>PERBAIKAN KEBOCORAN YANG DI AKIBATKAN DARI GENTENG ROOF</p> <p><i>REPAIR OF LEAKING RESULTING FROM THE TILES ROOF</i></p>	<p>CENDANA LANTAI 23/02</p> <p><i>CENDANA FLOOR 23/02</i></p>		